Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

Number ST02202LA

This Certificate issued to

Lakeview Holding, Inc. 6929 E. Shorecrest Drive Anaheim, CA 92807

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25* of the Federal Aviation Regulations. * (for Certification basis see Type Certificate Data Sheet)

Original Product Type Certificate Number:

Make: Dassault-Aviation

Model:

Falcon-50

Description of Type Design Change Installation of Universal Avionics Electronic Flight Instrument System (EFI-890R) with Engine Instrument Display System and Flight Management System (FMS) in accordance with FAA Approved IFR Avionics Master Data List, Document No. 08-F50-100, Revision "J", dated February 4, 2009, or later FAA approved revision.

Limitations and Conditions:

The approval of this installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration

Date of application: February 2, 2008

Date reissued: February 5, 2010, March 15, 2010

Date of issuance:

February 6, 2009

By direction of the Administrator

Date amended:

Manager, Systems and Equipment Branch, Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.